

OKLAHOMA MESONET/ARS QUALITY ASSURANCE REPORT

June 2005

Prepared by [Peter K. Hall, Jr.](mailto:pkhjr@mesonet.org) and [Janet E. Martinez](mailto:gamgr@mesonet.org)
pkhjr@mesonet.org and gamgr@mesonet.org

- The Mesonet Technicians were again busy in the month of June. A total of 193 trouble tickets were resolved last month!
 - At the ARS Fort Cobb Watershed, 6 more micronet sites were installed (F101, F104, F106, F107, F111, F114).
 - An initial installation of a 60 cm soil moisture sensor was performed at the Slapout site.
 - HMP-45C Temp/RelH sensors were installed at 8 additional Mesonet sites. The network-wide upgrade of these sensors has been completed.
 - Krypton hygrometers were removed from 4 Mesonet super sites. All kryptions have been removed from the network.
 - A bad data logger was replaced at the Bixby site. Data were minimally affected.
 - Additional work included the 13 PROM upgrades, 3 enclosure upgrades, as well as the scheduled rotations of 4 air temperature sensor pairs, 5 wind monitor nose cones, and 9 wind sentries.

- Lightning strikes occurred at the Altus base and the Wann repeater.

- The Burneyville site was downgraded from a super site to an OASIS site.

Mesonet QA Report for Standard Variables

Variable	Status	Ticket	Site	Remarks
TAIR	Current	11648	PORT	Sensor reporting dips in temperature of nearly 15°C
	Resolved	11392	ARD2	Cleaned and rewired sensor that was reporting biased temperature data
	Resolved	11614	NOWA	Replaced sensor that had developed a 1 deg C high bias
	Resolved	11479	WYNO	Replaced sensor that was reporting 15 deg C temperature dips
RELH	Resolved	11627	ALV2	Replaced sensor that had been reporting erratic relative humidity values
WDIR	Current	11652	MANG	Sensor reporting wind direction values that are not consistent with neighboring sites
WSPD	Resolved	11568	ANTL	Reinstalled prop that had been knocked loose during a squall line

PRES	Current	11771	MTHE	Sensor has developed a 1 mb high bias
	Resolved	11455	RETR	Cleaned tube of pressure sensor that had been plugged by insects
	Resolved	11559	FITT	Replace sensor that was reporting errors
SRAD	Resolved	11349	SLAP	Replaced sensor that had developed a low bias
	Resolved	11548	SPEN	Replaced sensor that had developed a low bias
RAIN	Resolved	11469	MARE	Cleaned spider webs out of bucket
	Resolved	11470	SEIL	Re-aligned gauge housing to prevent switch from getting stuck again
	Resolved	11542	TAHL	Cleaned spider webs out of bucket
TA9M	Current	11650	DURA	Sensor is hanging outside of radiation shield
	Resolved	11391	ARD2	Fixed wiring on sensor that was reporting erroneous data
WS2M	N/A			
TS10	Resolved	11549	CENT	Replaced sensor that had failed a water bath test
TB10	Resolved	11428	KETC	Replaced sensor that had been damaged by lightning
	Resolved	11405	SPEN	Replaced sensor that had reported 1 to 2 deg C temperature spikes
TS05	Current	11461	HOBA	Sensor has developed a high bias
	Resolved	11586	CENT	Replaced sensor that had failed a water bath test
	Resolved	11429	KETC	Replaced sensor that had been damaged by lightning
	Resolved	11249	SLAP	Returned sensor to correct depth
TB05	Current	11770	GOOD	Sensor appears to be exposed
	Current	11617	PUTN	Sensor reporting spiking and dipping soil temperature values
	Resolved	11427	KETC	Replaced sensor that had been damaged by lightning
TS30	Current	11468	HOLL	Sensor had developed a 3°C low bias
	Resolved	11505	BLAC	Replaced sensor that had been reporting temperature values that were spiking and dipping
	Resolved	11430	KETC	Replaced sensor that had been damaged by lightning
TR05	Current	11644	BESS	Sensor has stopped heating
	Current	11466	MAYR	Noise has developed in soil moisture sensor
	Current	11618	PUTN	Sensors reporting out-of-range data values
	Resolved	11421	KETC	Replaced sensor that had been damaged by lightning

TR25	Current	11681	BESS	Sensor has reported erratic data then stopped heating
	Current	11646	BIXB	Sensor has failed
	Resolved	11422	KETC	Replaced sensor that had been damaged by lightning
TR60	Current	11645	MIAM	Sensor has stopped heating
	Resolved	11423	KETC	Replaced sensor that had been damaged by lightning
TR75	Resolved	11424	KETC	Replaced sensor that had been damaged by lightning

ARS Little Washita Watershed QA Report

Variable	Status	Ticket	Site	Remarks
TAIR	Current	11772	A144	Sensor has developed a 2 °C high bias
	Resolved	11624	F113	Rewired sensor that was reporting erroneous data
RELH	N/A			
SRAD	N/A			
RAIN	Resolved	11558	A147	Cleaned spider webs out of bucket
	Resolved	11462	A156	Replaced switch that had failed
TS05	N/A			
TS10	Current	11653	A150	Sensor has developed a high bias
TS15	N/A			
TS30	N/A			

ARS Ft. Cobb Watershed QA Report

Variable	Status	Ticket	Site	Remarks
TAIR	Resolved	11624	F113	Rewired sensor that was reporting erroneous data
RELH	N/A			
SRAD	N/A			
RAIN	N/A			
TS05	N/A			
TS10	N/A			
TS15	N/A			
TS30	N/A			
VW05	N/A			
VW25	N/A			
VW45	N/A			

“Current” tickets are the unresolved tickets as of the last day of the month OR those tickets added based on the Monthly QA analysis.

“Resolved” tickets are the sensor problems that were fixed during the entire month.

Variable	Description
TAIR	Air temperature measured at 1.5 meters
RELH	Relative humidity measured at 1.5 meters
WDIR	Wind direction measured at 10 meters
WSPD	Wind speed measured at 10 meters
PRES	Pressure
SRAD	Incident solar radiation
RAIN	Rainfall
TA9M	Air temperature measured at 9 meters
WS2M	Wind speed measured at 2 meters
TS10	Soil temperature measured at 10 cm under native sod
TB10	Soil temperature measured at 10 cm under bare soil
TS05	Soil temperature measured at 5 cm under native sod
TB05	Soil temperature measured at 5 cm under bare soil
TS15	Soil temperature measured at 15 cm under native sod

TS30	Soil temperature measured at 30 cm under native sod
TR05	Soil moisture: Calibrated DeltaT measured at 5 cm under native sod
TR25	Soil moisture: Calibrated DeltaT measured at 25 cm under native sod
TR60	Soil moisture: Calibrated DeltaT measured at 60 cm under native sod
TR75	Soil moisture: Calibrated DeltaT measured at 75 cm under native sod
VW05	Soil moisture: Volumetric water content measured at 5 cm under native sod
VW25	Soil moisture: Volumetric water content measured at 25 cm under native sod
VW45	Soil moisture: Volumetric water content measured at 45 cm under native sod