

OKLAHOMA MESONET/ARS QUALITY ASSURANCE REPORT
October 2000

Prepared by Chris Fiebrich
gamgr@mesonet.org

Mesonet QA Report for Standard Variables	
TAIR	Current: #5323 TIPT Sensor has 6 C high bias Resolved:
RELH	Current: #5293 CATO Reporting 105% or higher Current: #5316 WEBB Reporting 40% low bias Current: #5332 MEDI Monthly QA indicates 5% high bias Resolved: #5264 WEBB Replaced sensor with 5-10% high bias
WDIR	Current: Resolved:
WSPD	Current: Resolved:
PRES	Current: Resolved:
SRAD	Current: #5070 HOOK Sensor found to be 6.5% high during Spring Pass 2000 comparison Current: #5072 KETC Monthly QA indicates 5-10% high bias Current: #5091 WIST Sensor found to be 5.5% low during Spring Pass 2000 comparison Current: #5097 BESS Sensor found to be 10% high during Spring Pass 2000 comparison Current: #5099 MEDF Sensor found to be 8% low during Spring Pass 2000 comparison Current: #5101 WALT Sensor found to be 10% low during Spring Pass 2000 comparison Current: #5111 GOOD Sensor found to be 6.7% high during Spring Pass 2000 comparison Current: #5115 FREE Sensor found to be 6% high during Spring Pass 2000 comparison Current: #5159 FAIR Sensor stuck at 0 Resolved:
RAIN	Current: #5297 BREC Under-reported rain event Resolved: #5272 BLAC Replaced bad switch Resolved: #5277 STIL Gauge checked and no problem found after apparent under-reporting Resolved: #5278 BRIS Removed spider web that prevented gauge from tipping Resolved: #5296 KETC Replaced bad gauge Resolved: #5314 ACME Replaced bad switch

TA9M	Current: Resolved:
WS2M	Current: Resolved:
TS10	Current: #5178 MAD1 Sensor sporadically reports +5 C offset Current: #5281 FTCB Stuck at -273.1 C Resolved: #5279 BIXB Sensor found to have 1 C cool bias
TB10	Current: #5216 PUTN Sensor erratic and dropping to as low as -17.2 C Current: #5282 FTCB Stuck at -273.1 Resolved: #5261 WEST Repaired excitation wire
TS05	Current: #5194 FAIR 5 C cool bias Current: #5283 FTCB Stuck at -273.1 C Resolved: #5262 BRIS Sensor found to have 5 C cool bias Resolved: #5263 BIXB Sensor found to have 2 C warm bias
TB05	Current: #5215 PUTN Sensor erratic and dropping to as low as -87.5 C Current: #5284 FTCB Stuck at -273.1 C Resolved:
TS30	Current: #5285 FTCB Stuck at -273.1 C Current: #5301 WASH 9 C warm bias Resolved: #5273 APAC Replaced gopher-damaged sensor

ARS QA Report	
TAIR	Current: Resolved: #5180 A182 Replaced sensor with 2.5 C warm bias
RELH	Current: Resolved:
SRAD	Current: #5255 A151 Mesocomp found 6% difference Current: #5294 A166 Stuck at 1 W/m ² Resolved:
RAIN	Current: #5319 A182 Dramatically over-estimates rainfall Current: #5325 A156 Gauge appears to have over reported Current: #5324 A151 Gauge stuck at 0 during rain event Resolved: #5295 A155 Replaced switch found to be double tipping Resolved: #5232 A150 Replaced defective switch
TS05	Current: Resolved: #5243 A136 Replaced defective sensor Resolved: #5265 A135 Replaced sensor reporting erratically

TS10	Current: #5267 A111 Possible 3 C cool bias Resolved: #5266 A165 Corrected wiring problem
TS15	Current: #5318 A167 Stuck at -90 C Resolved:
TS30	Current: Resolved: #5157 A165 Replaced bad sensor

“Current” tickets are the unresolved tickets as of the last day of the month OR those tickets added based on the Monthly QA analysis.

“Resolved” tickets are the sensor problems that were fixed during the entire month.

Variable	Description
TAIR	Air temperature measured at 1.5 meters
RELH	Relative humidity measured at 1.5 meters
WDIR	Wind direction measured at 10 meters
WSPD	Wind speed measured at 10 meters
PRES	Pressure
SRAD	Incident solar radiation
RAIN	Rainfall
TA9M	Air temperature measured at 9 meters
WS2M	Wind speed measured at 2 meters
TS10	Soil temperature measured at 10 cm under native sod
TB10	Soil temperature measured at 10 cm under bare soil
TS05	Soil temperature measured at 5 cm under native sod
TB05	Soil temperature measured at 5 cm under bare soil
TS15	Soil temperature measured at 15 cm under native sod
TS30	Soil temperature measured at 30 cm under native sod